




LIKE 50 2T WIRING DIAGRAM



LIGHTING SW

OFF	Q	RE	TL	HL	PO
	N	O	O	O	O
	P	O	O	O	O
	N	O	O	O	O
	H	O	O	O	O
	COLOUR	B	BR	L/W	BR/W

START SW

FREE	ST	E
	O	O
	PUSH	O
	COLOUR	Y/R
		C

PASSING SW

HI	BAT
	O
	PASS
	COLOUR
	L
	B

HORN SW

HI	BAT
	O
	PUSH
	COLOUR
	LG
	B

COMB SW

LOCK	IS	E	BATZ
	O	O	O
	OFF	O	O
	ON	O	O
	COLOUR	R	B/W
		G	B

WINKER SW

L	R	NR
	O	O
	N	O
	R	O
	COLOUR	SB
		OR

DIMMER SW

HL	HI	LO
	O	O
	LO	O
	N	O
	HI	O
	COLOUR	B
		L
		W