

# Increase in output of MXU 500



Seat remove  
Air cleaner box remove

Bild 2.



Bild 3.



Retaining chip from the gas loosen  
Carburetors laterally pull away

Bild 4.



Reduction from the syphon remove

Bild 5.



Bild 6.



Vehicle again assemble.

No main jets etc. are to be changed